

Basin	JDE Job #	Sche Shot	Shot#	Segment #	MHA	MHB	Street(Work Location)	Measured Diameter (in)	Approved Thick (mm)	Measured Length (ft)	Measured MHA Depth (ft)	Host Pipe Material	Measured # Service	Pre-CCTV Reviewed By	Line Status
20-08-23										2391.00			14		
Mon 8-21										454.00			6		
Shot #: 173										206.00			3		
LS8	142424	2	173	245	62	58	Wilson Avenue	7.75	6	206.00	4.2	VCP	3	JD	RTL
Shot #: 227										248.00			3		
	142424	1	227	309	MH-54A	MH-54	Harding Avenue	7.75	6	248.00	3.5	VCP	3	JD	RTL
Tue 8-22										778.00			5		
Shot #: 175										300.00			1		
LS8	142424	4	175	248	51	49	Rigdeewood Avenue	7.75	6	300.00	7.5	VCP	1	JD	RTL
Shot #: 176										478.00			4		
LS8	142424	3	176	249	49	48	Barlow Avenue	7.75	6	395.00	8.2	VCP	4	JD	RTL
LS8	142424		176	250	48	47	Barlow Avenue	7.75	6	83.00	9.5	VCP	0	JD	RTL
Wed 8-23										332.00			3		
Shot #: 187										152.00			3		
LS8	142424	5	187	268	11	10	N. Banana River	7.75	6	152.00	4.4	VCP	3	JD	RTL
Shot #: 188										180.00			0		
LS8	142424	6	188	269	10	2	N. Banana River	10	6	79.00	12.4	VCP	0	JD	RTL
LS8	142424		188	270	2	1	N. Banana River	10	6	101.00	12.5	VCP	0	JD	RTL
Thr 8-24										659.00			0		
Shot #: 178										340.00			0		
LS8	142424	7	178	253	27	26	Publix Lot	10	6	340.00	16.5	VCP	0	JD	RTL
Shot #: 180										319.00			0		
LS8	142424	8	180	257	18	10	Behind Publix	10	6	319.00	16	VCP	0	JD	RTL
Fri 8-25										168.00			0		
Shot #: 177										168.00			0		
LS8	142424	9	177	251	47	28	N. Atlantic Avenue	7.75	6	168.00	11.3	VCP	0	JD	RTL