

JDE Job #	Scheduled Shot Order	Shot#	Segment #	MHA	MHB	Street(Work Location)	Measured Diameter (in)	Approved Thick (mm)	Measured Length (ft)	Measured MHA Depth (ft)	Host Pipe Material	Measured # Service	Pre-CCTV Reviewed By	Line Status
17-09-23									1601.00			13		
Wed 9-20									607.00			5		
Shot #: 193									607.00			5		
142424	4	193	276	70	71	S.Atlantic Avenue	7.75	6	296.00	4	VCP	3	JD	RTL
142424		193	277	71	79	S.Atlantic Avenue	7.75	6	311.00	5	VCP	2	JD	RTL
Thr 9-21									514.00			5		
Shot #: 189									205.00			4		
142424	6	189	271	63	64	Olive Street	7.75	6	205.00	4	VCP	4	JD	RTL
Shot #: 190									309.00			1		
142424	5	190	272	64	65	S. Orlando Avenue	7.75	6	309.00	4	VCP	1	JD	RTL
Fri 9-22									480.00			3		
Shot #: 191									480.00			3		
142424	7	191	273	67	66	S. Orlando Avenue	7.75	6	177.00	4	VCP	2	JD	RTL
142424		191	274	66	61	S. Orlando Avenue	7.75	6	303.00	4	VCP	1	JD	RTL