

Basin	JDE Job #	Sche Shot	Shot#	Segment #	MHA	MHB	Street(Work Location)	Measured Diameter (in)	Approved Thick (mm)	Measure d Length	Measured MHA Depth (ft)	Host Pipe Material	Measured # Service	Pre-CCTV Reviewed By	Line Status	Traffic Comments
<b>19-11-23</b>										1492.00			22			
<b>Mon 11-20</b>										529.00			8			
<b>Shot #: 141</b>										529.00			8			
LS 6	142424	1	141	198	139	138	S.Atlantic Avenue	7.75	6	329.00	5	VCP	5	JD	RTL	
LS 6	142424		141	199	138	137	S.Atlantic Avenue	7.75	6	26.00	6.4	VCP	1	JD	RTL	
LS 6	142424		141	200	137	80	S.Atlantic Avenue	7.75	6	174.00	6	VCP	2	JD	RTL	
<b>Tue 11-21</b>										654.00			10			
<b>Shot #: 138</b>										654.00			10			
LS 6	142424	2	138	195	83	140	S.Atlantic Avenue	7.75	6	326.00	6.5	VCP	5	JD	RTL	
LS 6	142424		138	196	140	82	S.Atlantic Avenue	7.75	6	27.00	7.3	VCP	1	JD	RTL	
LS 6	142424		138	197	82	80	S.Atlantic Avenue	7.75	6	301.00	7.1	VCP	4	JD	RTL	
<b>Wed 11-22</b>										309.00			4			
<b>Shot #: 136</b>										309.00			4			
LS 6	142424	3	136	193	85	84	S.Atlantic Avenue	7.75	6	309.00	5.2	VCP	4	JD	RTL	